




QUAIL CREEK M.U.D.

A RELIABLE SOURCE

515 Chukar Drive · Victoria, Texas 77905-4404 · (361)-572-0810 · FAX (361)-572-3993



**Failure to Submit a Disinfectant Level Quarterly Operating Report (DLQOR)
MONITORING, ROUTINE (DBP), MAJOR/CHLORINE**

The QUAIL CREEK MUD water system PWS ID 2350004 has violated the monitoring and reporting requirements set by the Texas Commission on Environmental Quality (TCEQ) in Title 30, Texas Administrative Code (30 TAC), Section 290, Subchapter F. Public water systems are required to properly disinfect water before distribution, maintain acceptable disinfection residuals within the distribution system, monitor the disinfectant residual at various locations throughout the distribution system, and report the results of that monitoring to the TCEQ on a quarterly basis.

Results of regular monitoring are an indicator of whether or not your drinking water is safe from microbial contamination.

This violation occurred in the monitoring periods of 2nd quarter of 2023.

We are taking the following actions to address this issue:

Reports will be submitted online in a timely fashion.

If you have questions regarding this matter, you may contact Daniel O. Jimenez at 361-572-0810.

Posted/Delivered on: October 31, 2023